



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**YK71KHR**

## Mercedes-Benz Actros 2545

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	17/01/2022	VIN	W1T96342320551095
Year	2022	Body Style	Tractor Unit
Mileage	666,061 Km Warranted	MOT Due	30/06/2026
Fuel Type	Diesel	Cab Type	BIGSPACE CAB
Colour	WHITE	Gearbox	AUTOMATIC
		Axle Combi	6x2
		Steering Combi	Mid-Lift
		Rear Suspension	Air

SLIDING 5TH WHEEL, MIRROR CAMS

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features



- Air conditioning

## Photos






MERCEDES IACTROS									
Model	ARTIC R	Year of Original Registration	Year of Manufacture	Power (kW)	Power (hp)	Weight (kg)	Weight (kg)	Weight (kg)	Weight (kg)
Description of original vehicle	1795122	2001	2001	4400	6000	44000	44000	44000	44000
Weight (kg)	24000	25000	25000	4400	6000	44000	44000	44000	44000
Weight (kg)	24000	25000	25000	4400	6000	44000	44000	44000	44000
Weight (kg)	24000	25000	25000	4400	6000	44000	44000	44000	44000
Weight (kg)	24000	25000	25000	4400	6000	44000	44000	44000	44000
Weight (kg)	24000	25000	25000	4400	6000	44000	44000	44000	44000
Weight (kg)	24000	25000	25000	4400	6000	44000	44000	44000	44000
Weight (kg)	24000	25000	25000	4400	6000	44000	44000	44000	44000
Weight (kg)	24000	25000	25000	4400	6000	44000	44000	44000	44000



## Condition Check



## Damage Photos



1: Wing osf  
Missing  
Replace

2: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



3: Wing Front Arch Extension os  
Scratched (Painted)  
Over 25mm Thru Paint

4: Wing Front Arch Extension os  
Scratched (Painted)  
Over 25mm Thru Paint



5: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK