

VEHICLE INSPECTION REPORT

WR68LOD

Ford Transit COURIER 1.5 TDCi

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 12/11/2018

Year 2018

Mileage 132,756 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0WXXTACWJB27458

Body Style Panel Van

MOT Due 15/01/2026

CAP Clean £2,575.00

CAP Average £2,250.00

CAP Below £1,750.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor
- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door osf
Rusted
Over 5mm



3: Door nsf
Dented
Over 30mm



4: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		-	Upholstery Condition		-
Seat Condition		-	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	